



NEXT
Environmental Inc.

Borehole Log: BH201/202

Project No.: HAR180101.01

Logged By: SM

Project: DSI - Phase 1

Client: Harmer Holdings Ltd.

Location

of Borehole: Adjacent to West Site Entrance

Site Address: 2636 Douglas Rd., Burnaby, BC

SUBSURFACE PROFILE				SAMPLE / BOREHOLE COMPLETION					
Depth	Symbol	Description	Depth/Elev.	Sample ID	Type	Lab	0100 300500 % LE 0 50 100	Borehole Completion	Depth
0		Ground Surface							0
0	■	ASPHALT	0.00						0
0.16	▨	SILTY SAND Medium grey Silty SAND, some gravel, loose, moist	0.16						1
1.52	▨	WOODWASTE (HOGFUEL) WOODWASTE (HOGFUEL), moist	1.52						2
1.68	▨	PEAT Medium brown PEAT, saturated	1.68						3
3.96		End of Borehole	3.96						4

Drilled By: Blue Max Drilling Inc.

Drill (Sample) Method: Solid Stem Auger

Drill Date: July 22, 2015

Depth to Water (below top) (m): 1.845 & 1.145

Top of Pipe (top)

Well Elevation (m): N/A

Surface Grade Elevation (m): N/A

Groundwater

Analysis: Yes (BH201)

Sheet: 1 of 1