

Project Name: Post Remedial Investigation
Project Number: 00232-01

MONITORING WELL: MW16-21
Location: 11445 124th Street

Coordinates

Easting: 508807.39
Northing: 5450880.47
Datum: NAD83 UTM Zone 10

Drilling Details

Drill Contractor: **On Track Drilling**
 Drill Date: **10-Mar-16**
 Drill Method: **Solid Stem Auger**
 Depth of Drilled Hole (mbgs): **6.1**
 Drillhole Diameter (mm): **50**

Well Installation Details

Final Depth of Well (mbgs): **5.18**
 Well Casing Material: **PVC**
 Well Casing Diameter (in): **2**
 Well Screen Slot Size: **10**

