

Project No: 8460201

Test Hole / Borehole I.D.: BHOS-7

Client: Rick Williams

Well I.D.: SWOS-7

Location on site: Sutherland Road (middle)

Location: 1502/1504 Sutherland Avenue

Logged by: RK

SUBSURFACE PROFILE			SAMPLE			GasTech Reading	Well Completion Details / Remarks
Depth	Symbol	Description	Type	I.D.	Flag for analysis	ppm 125 250 375 %LEL 10 30 50 70 90	
0		Ground Surface					<p>Water Level taken on Oct 31, 2007</p>
0 to 1		Clean brown SAND					
1 to 2		grey fine SAND, wet		BHOS7-1		2.5LEL	
2 to 3		coarse SAND/GRAVEL, wet, mild odor		BHOS7-2		12LEL	
3 to 4				BHOS7-3			
4 to 5				BHOS7-4			
5 to 6		End of Borehole		BHOS7-5			
6 to 7							
7 to 8							
8 to 9							
9 to 10							
10 to 11							
11 to 12							
12 to 13							
13 to 14							
14 to 15							
15 to 16							
16 to 17							
17 to 18							
18 to 19							
19 to 20							



Contractor: Kel Drilling  
 Operator(s): Kelvin and Keldon  
 Drill Method: Solid/hollow  
 Ground conditions:

Date: October 26, 2007

Time: 12:23

Temperature: 5C

Sheet: 1 of 1