



NEXT
Environmental Inc.

Borehole Log: BH204

Project No.: SAV020103.01

Logged By: RM

Project: Stage 2 PSI

Client: Savemore Plumbing Inc.

Location

of Borehole: Northwest corner of the Site.

Site Address: 8728-8750 Aisne Street, Vancouver, BC

SUBSURFACE PROFILE				SAMPLE					
Depth	Symbol	Description	Depth/Elev.	Number	Type	Lab	ppmv 0 100 300 500 ▲ % LEL ▲ 0 50 100	Borehole Completion Details	Depth
0		Ground Surface							0
0		SAND AND GRAVEL (Fill) Brown, SAND AND GRAVEL/SOILS, some silt, some organics, loose, dry.	0.00	BH204-1		-	0		0
0.61		SILT Light grey, SILT, few gravels, tight... ... moist to wet at 1.5m.	0.61	BH204-2		-	100		1
				BH204-3		-	5		2
				BH204-4		-	0		3
				BH204-5		-	5		4
				BH204-6		-	0		5
3		End of Borehole	3.05						3

Any use which a third party makes of this document, or any reliance on or decisions to be made based on it, are the responsibility of such third parties. CSAP/MOE/NEXT are not responsible for any use or modification of this document. CSAP/MOE/NEXT accept no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions taken based on this document.

Drilled By: Blue Max Drilling Inc.

Drill (Sample) Method: Solid Stem Auger

Drill Date: October 16, 2014

Depth to Water (below top) (m): 1.23

Top of Pipe (top)

Well Elevation (m): N/A

Surface Grade Elevation (m): Not surveyed

Groundwater

Analysis: Y

Sheet: 1 of 1