

2001 TEST HOLE LOGS

NUMBER	DEPTH (m)	LAYER DESCRIPTION	GROUND WATER	SAMPLE DEPTH (m)	PID (ppm)	ANALYSIS
TH01-1	0.0 - 0.1 0.1 - 0.5 0.5 - 3.4 3.4	Sandy GRAVEL (FILL), loose, trace fines, brown Mixed FILL, sand, gravel, clay, brick and coal fragments Silty CLAY, trace fine gravel Auger Refusal on possible bedrock	No seepage	0.3 0.7 2.3		metals, LEPH
TH01-2	0.0 - 0.15 0.15 - 0.4 0.4 - 4.5 4.5	Sandy GRAVEL (FILL), trace fines, brown Silty SAND (FILL), some organics Silty CLAY, trace sand and fine gravel, brown Auger Refusal on possible bedrock	Piezometer 0-3.6 Seal 3.6-4.4 Slotted	0.2 0.7 2.5		metals
TH01-3	0.0 - 0.3 0.3 - 0.8 0.8	Mixed (FILL), sand, silt, gravel with brick and concrete fragments Silty CLAY, trace sand, brown Auger Refusal on possible bedrock	No seepage	0.2		metals
TH01-4	0.0 - 0.1 0.1 - 0.6 0.6 - 1.5	Sandy GRAVEL (FILL), trace fines, loose, brown Silty SAND (FILL), some organics, trace coal Silty CLAY, trace sand, stiff to hard	No seepage	0.3 0.9		metals
TH01-5	0.0 - 0.2 0.2 - 0.4 0.4 - 1.5	Sandy GRAVEL (FILL), some silt, brown, compact Silty SAND (FILL), organic Silty CLAY, trace sand, brown, stiff to hard	No seepage	0.15 0.8		metals
TH01-6	0.0 - 0.1 0.1 - 0.5 0.5 - 5.1 5.1 - 6.7	Concrete Slab Silty SAND (FILL), organic Silty CLAY, trace fine sand, brown, stiff to hard Silty CLAY, trace fine sand, grey, firm	Piezometer 0-4.9 Seal 4.9-6.7 Slotted	0.3 0.8 2.2		metals
TH01-7	0.0 - 0.2 0.2 - 0.5 0.5 - 1.5	Sandy GRAVEL (FILL), trace fines, brown, compact Silty SAND (FILL), organic, trace coal fragments Silty CLAY, trace sand, brown, stiff to hard	No seepage	0.3 0.7		metals