

PROJECT: SHELL CANADA PRODUCTS LTD.
 ENVIROMENTAL ASSESSMENT

LOCATION: (See Figure):

BOREHOLE No.: 4

LOCATION: 7010 PIONEER AVENUE,
 AGASSIZ, B.C.

BOREHOLE TYPE:
 HOLLOW STEM AUGER

DIAMETER: 200mm

SAMPLE TYPE: CORE SPLIT SPOON SHELBY DISTURBED NO RECOVERY

ELEV. - DEPTH (m)	STRATIGRAPHY	STRATIGRAPHY PLOT	SAMPLE TYPE	SAMPLE NUMBER	VAPOR LEVEL				N VALUE	WATER LEVEL	PIEZOMETER INSTALLATION ADDITIONAL LAB. TESTING
					● %LEL	▲ ppm.	▲ 100	● 20			
0.0	Asphalt.										51mm ø Solid PVC pipe.
0.5	Loose dark brown silty SAND & GRAVEL, some cobbles. No product odor.										
1.0				S10							
1.5	Compact greyish brown silty fine SAND to fine sandy SILT. Strong product odor.										
2.0											
2.5				S11							
3.0	Grey SAND & GRAVEL, some cobbles. Strong product odor.										
3.5											
4.0											
4.5											
	End of borehole @ 5.0m.										

MORROW RECOVERY SYSTEMS INC.
 North Vancouver, B.C.

DATE: 90.03.12
 LOGGED BY: J.M.B.

JOB NO.: R10-134

SHEET 4 OF 7