



NEXT
Environmental Inc.

Borehole Log: BH201

Project No.: SHA050104.01/02

Logged By: KB

Project: Detailed Site Investigation

Client: Shaughnessy Motors Ltd.

Location
of Borehole: AoEC 1

Site Address: 2789 Shaughnessy Street, Port Coquitlam

SUBSURFACE PROFILE				SAMPLE				
Depth	Symbol	Description	Depth/Elev.	Number	Type	Lab	• ppmv • 0 100 300 500 ▲ % LEL ▲ 0 50 100	Borehole Completion Details
0		Ground Surface						
0		Asphalt	0.000					
1		Sand and Gravel Fill Brown SAND and GRAVEL FILL with cobble, loose, damp, no odour, no staining.		201-1			10	
2								
3								
4		Silty Sand Dark brown SILTY SAND with cobble, soft, moist, slight hydrocarbon odour, no staining.	1.219	201-2			15	
5				201-3		B/V, EPH	70	
6		Sand and Gravel Grey SAND and GRAVEL with cobbles.	1.676					
7								
8								
9		Poor sample recovery.		201-4			10	
10								
11				201-5			10	
12								
13								
14		Saturated at 4.3 m.		201-6		B/V, EPH	20	
15								
16				201-7			40	
17								
18								
19				201-8			55	
20		End of Borehole	6.096					
21								

Drilled By: Beck Drilling and Environmental Services Ltd.

Drill Method: Solid Stem Auger

Drill Date: December 15, 2005/January 12, 2006

Depth to Water
(below top) & Date: Not measured

Top of Pipe (top)

Well Elevation: Not measured

Surface Grade Elevation: 100.108 m

Groundwater

Analysis: None

Sheet: 1 of 1