

Ministry of Energy, Mines and Low Carbon Innovation

## Weekly Summary of Dangerous Occurrences

Sharing safety with the mining industry



## Dangerous Occurrences Reported for the Week of November 7<sup>th</sup> to 13<sup>th</sup>

- **1.** Surface Mobile Equipment Out of Control: The operator of a light duty vehicle lost control due to winter driving conditions and slid into another light duty vehicle.
- 2. Surface Electrical Arc Flash: A worker's wrench contacted an un-discharged capacitor in the high voltage cabinet of a haul truck. The resulting arc flash knocked the worker back and caused them to have ringing and pain in the ears, and light sensitivity.
- **3.** Surface Mobile Equipment: A hose failure on a drill released pressurized air, rocks, and water, hitting a worker's calf and causing soft tissue injuries.
- 4. Surface Operations: A worker adjusting a sling got their hand caught and fractured their thumb.
- **5. Surface Mobile Equipment:** During operation an excavator fire resulted from an engine failure. The operator was able to safely exit and extinguish the fire with help from others.

**Comments:** As we move into winter, remember to be:

- Alert for changing conditions during the work shift;
- Aware of new seasonal specific tasks such as shovelling snow that can cause overexertion injuries;
- Flexible and have flexible plans, and
- Prepared for unexpected events such as power outages and vehicle breakdowns.

For more information on winter driving visit Shift Into Winter, Winter Driving Tips & Safety for BC Drivers - Road Safety at Work, and Winter driving - WorkSafeBC.