

## Weekly Summary of Reportable Incidents

Sharing safety with the mining industry



- 1. Surface Mobile Equipment, Rollover: A vacuum truck was travelling to the mine site when it drove onto a soft gravel shoulder and rolled onto the driver's side.
- 2. Surface Mobile Equipment, Rollover: A loaded articulated truck was dumping material when the box tipped over.
- **3.** Falling Object: A drill operator was completing drilling work when a rock rolled from a nearby high wall, contacted the drill walkway guardrail, and entered the drill cab through the window.
- 4. Working at Heights, Falling Objects: A worker was testing a scaffolding connection point when a beam clamp assembly fell, which deflected, and contacted a worker on the side of the head, causing an injury.
- 5. Surface Mobile Equipment, Out of Control: A loaded haul truck was travelling down a road when it lost control and came to a stop on a berm.

Comments: Falling object can cause serious injury, even over short distances! Ensure workers perform risk assessments to identify fallingobject hazards.