



Centre of bridge to river right approach



River left approach to Bridge



Centre of bridge to river left approach



River right approach to Bridge



Upstream from Crossing



Downstream Profile



Upstream Profile



Downstream from Crossing



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Stringers



Bearing



Right Bank Abutment when facing downstream

QC-7911

Spirit Lake Trail km

2017 Inspection

